

**INDEPENDENT VOLVO
SERVICE**

1401 THIRD ST. N.W.
ALBUQUERQUE NM 87102
ALBUQUERQUE NM 87102

(505) 247-9771

ivs@lobo.net

Estimate: **26864** 10/23/2007

AUTO SHOPPE IMPORTS

6616 Central Ave. Se
Albuquerque NM 87108

10192007 (505) 250-1120 p

**2002 Volvo V70 License: 3117/2042 Odometer: 104099 Vin: YV1SW58D421192042
B5244T3 AW55-50/51SN ABS ASH-GOLD**

PRESALE INSPECTION AND BASIC MAINTENANCE

Labor performed on this job:

Labor 1 Labor Rate: \$85.00 \$85.00
INSPECT VEHICLE IN ORDER TO DETERMINE SERVICE
NEEDS BEFORE SALE

8

Parts: \$0.00
Labor: \$85.00
Job Subtotal: \$85.00

SERVICE WORK

Labor performed on this job:

Labor 1.5 Labor Rate: \$85.00 \$127.50
Oil and filter service. Replaced air filter, cabin air filter, lr
taillight bulbs and wiper blades. Check fault codes: none
found. Check brakes: front and rear 60% remaining.

8

Parts required on this job:

Haz Mat Fee	6	\$0.25	\$1.50
10W30	6	\$2.20	\$13.20
OIL FILTER, INSERT 70 99-04 V70 99+, S80, S40 -MID04, V40 -04, S60, XC90 ALL	1	\$8.42	\$8.42
WASHER, DRAIN PLUG - ALUMINIUM 850, 960, 70, 90, S80, 40, V50, S60, XC90	1	\$0.64	\$0.64
GASKET, OIL FILLER CAP 200 4CYL, 700 4CYL, 900, 850, 90	1	\$1.50	\$1.50
AIR FILTER, V70 01+, S60	1	\$20.50	\$20.50
FILTER, FRESH AIR CABIN S80, V70 01+, S60, XC90	1	\$25.23	\$25.23
BULB, PARK LIGHTS/TAIL LIGHT 200 75-84, 740/760 83-84, 780, 850, S80	2	\$2.86	\$5.72
WIPER BLADE KIT, FRONT (2 PCS) V70 01- 04, S80 -03, S60 -04, XC90 -04	1	\$26.62	\$26.62

Parts: \$103.33
Labor: \$127.50
Job Subtotal: \$230.83

TIMING BELT SERVICE S/V70

Labor performed on this job:

Labor 2.5 Labor Rate: \$85.00 \$212.50

Replace the camshaft timing belt and ancillary parts as part of necessary periodic maintenance. This includes the

examination and replacement of covers, seals, and

tensioner as needed. All setting and adjustment of timing,

mixture, base idle and the cleaning of the engine breather.

8

Labor 1 Labor Rate: \$85.00 \$85.00

Replace water pump and coolant in conjunction with timing belt service.

8

Parts required on this job:

TENSIONER KIT, 1 \$185.18 \$185.18

TIMING BELT 70 97-98
W/ MAN TENS ENG#

1266128+, C/S70 99-04,

V70 99+, S60, 40 -04,

S80 04 5CYL, XC90 -04

5CYL (CK ENG#S -
3188688)

WATER PUMP, 850 93- 1 \$144.89 \$144.89

98, 960 92-94 6CYL, 70,
40, S60

COOLANT 1 \$9.50 \$9.50

Parts: \$339.57

Labor: \$297.50

Job Subtotal: \$637.07

REAR BRAKES

Labor performed on this job:

Labor 1 Labor Rate: \$85.00 \$85.00

Remove and machine rear brake rotors, reinstall.

8

Parts required on this job:

MACHINE BRAKE ROTOR 2 \$15.00 \$30.00

Parts: \$30.00

Labor: \$85.00

Job Subtotal: \$115.00

MASTER KEY WITH SOFTWARE DOWNLOAD

Labor performed on this job:

Labor 0.5 Labor Rate: \$85.00 \$42.50

Supply new master key and download software to make it operate

1

Parts required on this job:

PASS KEY 1 \$51.98 \$51.98

IGNITION KEY APPL. 1 \$35.00 \$35.00

Parts: \$86.98

Labor: \$42.50

Job Subtotal: \$129.48

EMISSION TEST(FLEET)

Labor performed on this job:

Labor 0.1882 Labor Rate: \$85.00 \$16.00

PERFORM BERNILILLO COUNTY EMISSION TEST

1

Parts: \$0.00

Labor: \$16.00

Job Subtotal: \$16.00

SHOP INFORMATION AND SUPPORT

Labor performed on this job:

Labor 0.24 Labor Rate: \$85.00 \$20.40

The information age has arrived and it is expensive. We currently spend in excess of \$1000 monthly for current Volvo service information and hardware associated with its use. Additionally, the myriad of items never invoiced i.e. Hardware, chemicals, cleaner and other supplies continue to escalate in cost. Our shuttle service is another new expense. This surcharge is to help recover a portion of these costs without increasing our labor rate. Thank you for your understanding and support.

9

Parts: \$0.00

Labor: \$20.40

Job Subtotal: \$20.40

Estimate of Repair

Parts: \$559.88

Labor: \$673.90

Discounts: **(\$148.05)**

Subtotal: \$1,233.78

Tax: \$0.00

Total: \$1,085.73